

Concentration of impurities in GaSe (by GDMS)

Element		[at,%]	Element		[at,%]	Element		[at,%]	Element		[at,%]	Element		[at,%]
Li		0,000010000	Sc	<	0,000000100	Y	<	0,000000100	Ce	<	0,000000100	Os	<	0,000000100
Be	<	0,000001000	Ti	<	0,000000100	Zr	<	0,000000100	Pr	<	0,000000100	Ir	<	0,000000100
B	<	0,000000500	V	<	0,000000100	Nb	<	0,000000100	Nd	<	0,000000100	Pt	<	0,000000100
C		0,000007300	Cr		0,000002000	Mo	<	0,000000200	Sm	<	0,000000100	Au	<	0,000001000
N		0,000007000	Mn		0,000001600	Ru	<	0,000000200	Eu	<	0,000000100	Hg	<	0,000001000
O		0,000011000	Fe		0,000009000	Rh	<	0,000000500	Gd	<	0,000000100	Tl	<	0,000001000
F	<	0,000001000	Co		0,000000500	Pd	<	0,000000500	Tb	<	0,000000100	Pb	<	0,000001000
Na		0,000004000	Ni		0,000002200	Ag	<	0,000003000	Dy	<	0,000000100	Bi	<	0,000001000
Mg		0,000005000	Cu		0,000012000	In	<	0,000005000	Ho	<	0,000000100	Th	<	0,000001000
Al		0,000009500	Cd		0,000013000	Sn	<	0,000000500	Er	<	0,000000100	U	<	0,000000050
Si		0,000023000	Zn	<	0,000014000	Sb	<	0,000000200	Tm	<	0,000000100	Ca	<	0,000000040
P	<	0,000000500	Ge	<	0,000001000	S	<	0,000000300	Yb	<	0,000000100	Rb	<	0,000000200
Te		0,000014000	As	<	0,000001500	I	<	0,000000100	Lu	<	0,000000100	La	<	0,000000300
Cl		0,000001100	Sr	<	0,000000500	Cs	<	0,000000200	Hf	<	0,000000100	Re	<	0,000000100
K	<	0,000000700	Br	<	0,000002000	Ba	<	0,000001000	W	<	0,000000100			

0,000095600

0,000059600

0,000012000

0,000001500

0,000006990

0,000175690 TOTAL